Other terms and conditions can be had from the office of the Executive Engineer during office hours on

	Estimated Cost	Earnest Money	Cost of B.O.Q.	Time of Completion
Repair/renovation and oil bound distemper of inside in V.C.'s Secretariat-cum-residence.     Repair, textured exterior paint of out side and APP on roof of V.C's	Rs.14.41,922/-	Rs. 28,900/-	Rs. 2,500/-	Twenty one days
residence and staff Qr.in the cam of V.C's residence. Repair, renovation and painting v of Guard room, Compound wall is	pus Rs.14,14,973/- vorks	Rs.28,300/-	Rs. 2,500/-	Twenty one days
filling of local sand in the campu  V.C. residence.	s of Rs. 8,29,582/-	Rs. 16,600/-	1,250/-	Fifteen days.

--/Dated, the D 5 / 86 / 2020 mo No. Engg/D. Eng. 1) . 2260 Copy forwarded to Sri Kishore Kumar, J.E./Secretary to V.C./S.O., Pro-V.C. Office S.O. Registrar Office University Notice (University web site waw, brabu.net B.R.A.B.U...Muzaffarpur for information and wide publicity.